

TOC

Wire EDM Post Variables	2
Introduction	2
Post Variables for Wire EDM Machines	2
Commands	2
Description	2
Variables	3
Part Setup	3
Positioning	4
Arcs	5
Line Numbers	6
Sub Programs	6
Comments	6
G Codes	7
M Codes	7
Cutting Parameters	8
Cutting Conditions	9
Feed Rate	9
Offset	9
Taper	10
Start Hole (Start Hole Drilling)	10
Script File (Agie 123 with Jobs)	10
Script File (AgieVision)	10
Agie	13
Sodick	13
Charmille	13
Ona	13
Wire Guides	13
Misc Characters	14
Misc Variables	14

WIRE EDM POST VARIABLES

Introduction

This topic contains all of the Wire EDM post variables used for post scripting or customizing posts processors.

Post Variables for Wire EDM Machines

Commands	Description
oldvars	use old position (previous move) variables and misc. variables.
newvars	use new position (current move) variables and misc. variables.
force_x	force the X value to be output next time even if modal.
force_y	force the Y value to be output next time even if modal.
force_z	force the Z value to be output next time even if modal.
force_xl	force the X value of lower contour of 4 Axis part to be output next time even if modal.
force_yl	force the Y value of lower contour of 4 Axis part to be output next time even if modal.
force_xu	force the X value of upper contour of 4 Axis part to be output next time even if modal.
force_yu	force the Y value of upper contour of 4Axis part to be output next time even if modal.
force_u	force the U value of upper contour of 4Axis part to be output next time even if modal.
force_v	force the V value of upper contour of 4Axis part to be output next time even if modal.
memo_xmove	Memorize the current X movement for use later.
memo_ymove	Memorize the current Y movement for use later.
memo_umove	Memorize the current U movement for use later.
memo_vmove	Memorize the current V movement for use later.
memorize_rethread_point	Output code to memorize current location for auto rethread (Sodick).
memorize_line_number	Memorize sequence number for use later.
memorized_line_number	Use memorize sequence number.
debug_on	Turns on automatic debug comments in post output.
debug_off	Turns off automatic debug comments in post output.
exit_if_glue_stop	Ignore the rest of the current contour if on glue stop. Used for Agie.
start_add_block_delete	Add block delete to all lines until stop_add_block_delete is used

stop_add_block_delete	Stop adding block delete that started from using start_add_block_delete
force_no_add_spaces	Force no spaces even when default is set to add spaces.
default_add_spaces	Set add spaces back to condition before force_no_add_spaces was called.
out_ctc_variables	Output cutting conditions variables. Usually at the beginning of the program.
pass_specific	Output start of pass block (Rough block for rough cut, 1st skim block for 1st skim etc).

Variables

Part Setup

absolute_coord	Output code to set coordinates to absolute mode (G90). Code defined in "G Codes/Absolute Coord:".
incremental_coord	Output code to set coordinates to incremental mode (G91). Code defined in "G Codes/Incremental Coord:".
absolute_coord_no_code	Set output mode to absolute, do not output G Code.
incremental_coord_no_code	Set output mode to incremental do no output G Code.
work_coord	Output work coordinates when it changing work pieces. (G54 etc) Code defined in "G Codes/Work offsets".
pattern_work_coord	Output work coordinates for pattern contours. (G54 etc) Code defined in "G Codes/Work offsets".
zero_set_xp_yp	Output code to set current work coordinate to programmed zero (G92X__Y__). Code defined in "G Codes/Coord zero set:".
zero_set_xr_yr	Output code to set current work coordinate to current cycle start point (G92X__Y__). Code defined in "G Codes/Coord zero set:".
zero_set	Output set zero command with out XY values (G92). Code defined in "G Codes/Coord zero set:".
metric_mode	Set output mode to metric.
inch_mode	Set output mode to inch.
metric_mode_no_code	Set output mode to metric without G code.
inch_mode_no_code	Set output mode to inch without G code.
ref_plane	Output reference plane value with prefix (Charmille). Prefix defined in "Prefixes/Reference plane".
part_height	Output workpiece height with prefix. Prefix defined in "Prefixes/Part height".
machining_mode	Output code for machining mode (no taper, taper, 4axis)
work_plane_height	Output work plane height. Determined by feature settings (Primary shape or Stock height, and use of land and taper).
incr_taper_height	Output incremental taper height from land, or primary feature shape.
taper_height	Output taper height.
two_axis_with_taper_start	Output code for two axis taper start.
two_axis_with_taper_end	Output code for two axis taper end.

Positioning	
xr	Output rapid position x with prefix (X1.25) (X prefix hard coded).
yr	Output rapid position y with prefix (Y1.25) (Y prefix hard coded).
x_ur	Output upper guide rapid position x with prefix from post question 606.
y_ur	Output upper guide rapid position x with prefix from post question 607.
xr_no_output	X rapid value to previous move without outputting code.
yr_no_output	Y rapid value to previous move without outputting code.
xr_upper	Output rapid position x upper guide with prefix (X1.25) (X prefix hard coded).
yr_upper	Output rapid position y upper guide with prefix (Y1.25) (Y prefix hard coded).
zr_upper	Output rapid position z upper guide with prefix (Z1.25) (Z prefix hard coded).
xr_lower	Output rapid position x lower guide with prefix (X1.25) (X prefix hard coded).
yr_lower	Output rapid position y lower guide with prefix (Y1.25) (Y prefix hard coded).
zr_lower	Output rapid position z lower guide with prefix (Z1.25) (Z prefix hard coded).
xh	Output home position x with prefix (X1.25) (X prefix hard coded).
yh	Output home position y with prefix (Y1.25) (Y prefix hard coded).
xp	Output programmed zero x (X___). (X prefix hard coded).
yp	Output programmed zero y (Y___). (Y prefix hard coded).
prev_x	Output previous x (X___). (X prefix hard coded).
prev_y	Output previous y (Y___). (X prefix hard coded).
z_position_up	Output code for programmable z position up.
z_position_down	Output code for programmable z position down.
x_f	Output code for x feed value with prefix. (X prefix hard coded).
y_f	Output code for y feed value with prefix. (Y prefix hard coded).
u_f	Output code for u feed value with prefix. (U prefix hard coded).
v_f	Output code for v feed value with prefix. (V prefix hard coded).
u_f_incremental	Output code for incremental u feed value with prefix. (U prefix hard coded).
v_f_incremental	Output code for incremental v feed value with prefix. (U prefix hard coded).
u_f_incr_change	Output code for change in incremental u feed value with prefix. (U prefix hard coded).
v_f_incr_change	Output code for change in incremental v feed value with prefix. (V prefix hard coded).
u_f_angle_perpend	Output code for change in angle perpendicular to xy move (Pos angle to right)
v_f_angle_parallel	Output code for change in angle parallel to xy move (Pos angle forward)
x_lf	Output x value with prefix for lower shape in 4 Axis entity to entity programming.
y_lf	Output y value with prefix for lower shape in 4 Axis entity to entity programming.
x_uf	Output x value with prefix for upper shape in 4 Axis entity to entity programming.

y-uf	Output y value with prefix for upper shape in 4 Axis entity to entity programming.
thread_point_x	Output x value with prefix for thread point.
thread_point_y	Output y value with prefix for thread point.
x_start_hole_rapid	Output x value with prefix for rapid feed to edge of start hole.
y_start_hole_rapid	Output y value with prefix for rapid feed to edge of start hole.
first_rapid_x	Output x value with prefix memorized first rapid point.
first_rapid_y	Output y value with prefix memorized first rapid point.
first_rapid_z	Output z value with prefix memorized first rapid point.
x_first_cut	Output x value with prefix for entrance cut when special cutting conditions are used to enter contour.
y_first_cut	Output y value with prefix for entrance cut when special cutting conditions are used to enter contour.
skip_next_move	Skip next movement in order to output later. Used for line swapping in Agie.
output_xmemo	Output the x value that was memorized with memo_xmove.
output_ymemo	Output the y value that was memorized with memo_ymove.
output_umemo	Output the u value that was memorized with memo_xmove.
output_vmemo	Output the v value that was memorized with memo_xmove.
u0_on_no_taper	Output U0.0 on 2axis part when no taper is used.
v0_on_no_taper	Output V0.0 on 2axis part when no taper is used.
return_to_thread_point	Output block to return to thread point. Used at the end of a program.

Arcs

xcenter	Output x center of arc with prefix ("Format/Arc center type"). Prefix define "Prefixes/Arc x center:".
ycenter	Output y center of arc with prefix ("Format/Arc center type"). Prefix define "Prefixes/Arc y center:".
rcenter	Output Radius value of arc with prefix ("Format/Arc center type"). Prefix define "Prefixes/Radius value:".
arc_center	Output x, and y center of arc with prefixes ("Format/Arc center type"). Prefix define "Prefixes/Arc x center:" & "Prefixes/Arc x center:".
xcenter_lf	Output x arc center value with prefix for lower shape in 4 Axis entity to entity programming.
ycenter_lf	Output y arc center value with prefix for lower shape in 4 Axis entity to entity programming.
xcenter_uf	Output x arc center value with prefix for upper shape in 4 Axis entity to entity programming.
ycenter_uf	Output y arc center value with prefix for upper shape in 4 Axis entity to entity programming.
iso_radius	Output code setting an Iso radius value with prefix. Code define in "G

Codes/Iso radius:".

Line Numbers

n	Output next sequence number with prefix. Prefix hard coded to (N).
n_forced	Force output of next sequence number with prefix (N). Sequence number for set in "Format/sequence numbers:".
agie_100_n	Used to set the first line number prefix to : for agie 100.
seq_numbers_start	Set the current N sequence number to the sequence number start value.

Sub Programs

sub_call	Output subprogram call. Prefix defined in "Prefixes/Arc x center:".
sub_return	Output subprogram return. Prefix defined in "Prefixes/Arc y center:".
sub_num	Output subprogram number without prefix.
sub_num_no_prefix	Output subprogram number without prefix.
sub_num_with_prefix	Output subprogram number with prefix. Prefix defined in "Prefixes/Subprogram:".
pattern_contour_sub_start	Output pattern contour code for subprogram start.

Comments

comment_start	Output comment start. Code defined in "Misc parameters/Comment start:".
comment_end	Output comment end. Code defined in "Misc parameters/Comment end:".
system_comment	Output the automatic comment "FEATURE 1 CNT2X ROUGH CUT FORWARD"
feature_name_comment	Output Feature Name comment "2 AXIS CONTOUR1-RECTANGULAR DIE3"
pass_name_comment	Output pass name comment "ROUGH 1"
feature_pass_names_comment	Output Feature and pass names "2 AXIS CONTOUR1-RECTANGULAR DIE3 ROUGH1"
sub_comment	Output subprogram description comment.
output_date	Output the date in the form "Tue. 03/05/2002"
output_time	Output the current time in the form "11:35AM"
prog_n	Output program number without prefix (O0001). Hard code prefix ("O",prog_n)
prog_name	Output program name (file name of saved program on disk)
machine_make	Output machine manufacturers name as string.
machine_model	Output machine model name as string.
pass_name	Output pass name. (Used in comment)
feature_name	Output feature name. (Used in comment)
workpiece_name	Output workpiece name. (Used in comment)
user_defined_operation_pass_comment	Output the user defined comment for the pass defined in the User Comment tab of the operation dialog.

user_comment_1	Output the comment entered in part settings comment 1
user_comment_2	Output the comment entered in part settings comment 2
user_comment_3	Output the comment entered in part settings comment 3
user_comment_4	Output the comment entered in part settings comment 4
user_comment_5	Output the comment entered in part settings comment 5
user_comment_6	Output the comment entered in part settings comment 6
user_comment_7	Output the comment entered in part settings comment 7
user_comment_8	Output the comment entered in part settings comment 8
user_comment_9	Output the comment entered in part settings comment 9
user_comment_10	Output the comment entered in part settings comment 10
user_comment_11	Output the comment entered in part settings comment 11
user_comment_12	Output the comment entered in part settings comment 12
user_comment_13	Output the comment entered in part settings comment 13
user_comment_14	Output the comment entered in part settings comment 14
user_comment_15	Output the comment entered in part settings comment 15
user_comment_16	Output the comment entered in part settings comment 16

G Codes

feed_move	Set movement to feed and output feed move command (G01). Value defined in "G Codes/Feed move:".
rapid_move	Set movement to rapid and output rapid move command (G00). Value defined in "G Codes/Rapid move:".
cc	Output code for Cutter compensation. Codes defined in "G Codes".
measurement	Output measurement mode (inch/metric). Inch defined in "G Codes/Inch mode:" & "G Codes/Metric mode:".
g_taper	Output Code for taper cutting on. (At present hard coded to G51,G52 will add questions).
g_arc_move	Output G code for arc moves. G02, G03 hard coded.
g_lower	Output G code for lower shape in 4 Axis entity to entity programming (G01, G02, G03).
g_upper	Output G code for upper shape in 4 Axis entity to entity programming (G01, G02, G03).
four_axis_xyuv_start	Output code to start 4 axis xyuv cutting. Code defined in "G Codes/4axis start".
four_axis_xyuv_end	Output code to end 4 axis xyuv cutting. Code defined in "G Codes/4axis end".

M Codes

end_of_file	Output end of file code (M02). Code define in "M Codes/End of file:".
stop	Output stop code (M00). Code define in "M Codes/Stop:".

optional_stop	Output code for Optional Stop (M01). Code define in "M Codes/Optional stop:".
stop_on_rough	Allow a stop to output if on rough cut and no glue stop
stop_tab_no_submerged	Output stop code if contour is tab cut when not in submerged machining.
stop_no_submerged	Output stop code if in submerged machining.
stop_no_autothread	Output stop code if no autothreading.
stop_for_tab_forced	Force the output of stop code on tab cut.
optional_stop_last_skim	Allow a optional stop to output on last skim pass
stop_for_tab	Output stop code for tab cut.
optional_stop_for_tab	Output optional stop for tab cut.
stop_die_on_rough_no_tab	Output Stop code at the end of the rough cut on a Die when no tap cut is used.
stop_on_rough_no_coreless	Output Stop code at the end of the rough cut except for the rough cut of a coreless cut.
optional_stop_die_on_rough_no_tab	Output Optional Stop code at the end of the rough cut on a Die when no tap cut is used.
optional_stop_on_rough_no_coreless	Output Optional Stop code at the end of the rough cut except for the rough cut of a coreless cut.
optional_stop_on_rough	Output Optional Stop code at the end of all rough cuts.
stop_last_skim	Output Stop code at the end of the last skim cut.
optional_stop_for_tab_forced	Output Stop code on tab cut, and force the output even if machine is stoped.
optional_stop_on_first_glue_stop	Output Stop code on first glue stop.
optional_stop_no_autothread	Output Stop code when not auto threading is used.
optional_stop_no_submerged	Output Stop code when not using submerged machining.
stop_for_tab_with_leadout_forced	Output Stop code on tab cut with leadout forced.
optional_stop_for_tab_with_leadout_forced	Output Optional Stop code on tab cut with leadout forced.
stop_on_first_glue_stop	Output Stop code on first glue stop.
stop_no_output	Set the internal stop code varialbe to Stop, but do not output code.
high_pressure_pump_on	Output code to turn high pressure pump on. Code define in "M Codes/High pressure on:".
high_pressure_pump_off	Output code to turn high pressure pump off. Code define in "M Codes/High pressure off:".
cut_wire	Output code to cut wire. Code define in "M Codes/Wire cut:".
thread_wire	Output code to thread wire. Code define in "M Codes/Wire thread:".

Cutting Parameters

submerged	Output code to fill tank if submerged machining is available and active.
wire_speed	Output code for wire speed if #522 is y. Prefix defined in question 611.

wire_tension	Output code for wire tension if #522 is y. Prefix defined in question 612.
generator_reg_num	Generator register number for Agie.
offset_reg_num	Offset register number.
flushing_reg_num	Flushing register number for agie.
angle_reg_num	Angle register number for agie.
wire_offset_force	Force the output of the "wire_offset" variable.
wire_offset_taper	Force the output of the "offset_taper" variable.
wire_offset_zero	Force the output of the "offset_zero" variable
ctc_register	Output the code for the current Cutting Conditions Register.
ctc_value	Output the Cutting Conditions value without prefix.
rapid_feed_rate	Output the feed rate using the rapid feed rate value.

Cutting Conditions

cutting_cond_first_cut	Output code for cutting condition for entrance cut (power setting). Prefix define in "Prefixes/Cutting cond:".
cutting_cond	Output code for setting cutting conditions (power setting). Prefix define in "Prefixes/Cutting cond:".

Feed Rate

feed_rate	Output code for feed rate.
start_hole_feed_rate	Output code for rapid feed rate to edge of start hole.
feed_rate_first_cut	Output code for entrance cut feed rate.
feed_rate_force	Force the output of the "feed_rate" variable.

Offset

out_offset_variables	Output offsets register variables. (Used only if set to use variables for offset "Misc parameters/Taper-offset").
wire_offset	Output code to set wire offset. Codes defined in "G Codes/Offset left:", & "G Codes/Offset right:".
cancel_offset	Output cancel wire offset in 2Axis. Code defined in "G Codes/Cancel offset:".
cancel_offset_4axis	Output cancel wire offset in 4Axis. Code defined in "G Codes/Cancel 4axis offset:".
agie_wire_offset	Output code to set wire offset for agie machines. Prefix defined in "Prefixes/Wire offset:".
set_offset_register	Output code calling an offset register to set wire offset.
offset_register	Output code for the current offset register.
offset_value	Output offset amount.

Taper

out_taper_variables	Output taper angles as register variables. (Used only if set to use variables for taper "Misc parameters/Taper-offset".
cancel_taper	Output code for cancel taper. Code defined in "G Codes/Cancel taper:".
taper_angle	Output code to set taper angle. See taper format setting in "Misc parameters/Taper-offset".
taper_zero	Output taper zero degrees. Used to initialize taper to zero at the beginning of program.
taper_register	Output taper register number when taper is output using registers.
taper_value	Output taper angle.
taper_mode	Output taper mode (Left, Right, Off).
taper_angle_no_prefix	Output taper angle without prefix.
force_taper_zero_on_taper	Force the output of a taper of 0.0, When the set taper value is not 0.0.

Start Hole (Start Hole Drilling)

drill_sub_calls	Output drill subroutine call for making start hole.
drill_end_of_file	Output drill end of file for making start holes.
drill_subprogram	Output drill sub program with hole positions.
drill_program	Output drill positions without sub programs.
z_drill	Output Z value for drilled hole.
z_clearance	Output Z clearance for positioning between drilled holes.

Script File (Agie 123 with Jobs)

agie_123_job_xr	Output X rapid block for agie 123 with jobs.
agie_123_job_yr	Output Y rapid block for agie 123 with jobs.
iso_file_path	Output the NC sub folder for the ISO file if user has selected NC files to create sub folder.
tech_file_name	Output the Technology file name.
tech_file_path	Output the Technology file path.
contour_direction	Output the contour chain direction (CCW or CW).
rough_pass_direction	Output the Rough pass contour direction (CCW or CW).
agie_123_pass_direction	Output the contour direction (CCW or CW) using logic based on which pass is being cut.

Script File (AgieVision)

file_path	File path for all files when using script format.
open_script_file	Open the script file.
close_script_file	Close the script file.

open_iso_file	Open Iso file.
close_iso_file	Close Iso file.
iso_file_name	Iso file name.
set_to_nc_file	Set all writing functions to the nc file.
set_to_iso_file	Set all writing functions to the iso file.
set_to_script_file	Set all writing functions to the script file.
set_to_sbr_file	Set all writing functions to the sbr file.
iso_file	Iso file name.
script_file	Script file name.
material_name	Material name.
wire_name	Wire name
punch_die_open	Output feature type (punch, die, open contour) for Agie Vision.
entry_mode	Output leadin/leadout mode for Agie Vision.
exit_mode	Output exit mode for Agie Vision.
stp_number	Start point number.
number_of_skims	Output number of skim passes.
tab_width	Output tab width.
reverse_tabs	Output setting for reverse tab cuts.
output_sub_calls	Output subprogram call line (" camw1");
output_sub_def	Output subprogram define line ("sub camw1");
output_sub_number	Output the subprogram number ("1").
zero_position_x	Work piece zero X value (ID_POSX).
zero_position_y	Work piece zero Y value (ID_POSY).
zero_position_z	Work piece zero Z value.
return_plane_distance	Work piece machining return Plane (ID_VALRETP).
security_plane_distance	Work piece machining security Plane (ID_VALSECP).
part_length	Work piece length (ID_DIML).
part_width	Work piece length (ID_DIMB).
priority_number	Machining order priority number (ID_PRIORITY).
quality_name1	Output quality name for Normal cut and land cut for agie vision.
quality_name2	Output quality name for Taper cut of land and taper for agie vision.
work_condition1	Output work condition for Normal cut and land cut for agie vision.
work_condition2	Output work condition for Taper cut of land and taper for agie vision.
ra_value1	Output Ra value for Normal cut and land cut for agie vision.
ra_value2	Output Ra value for Taper cut of land and taper for agie vision.
te_value1	Output Te value for Normal cut and land cut for agie vision.
te_value2	Output Te value for Taper cut of land and taper for agie vision.
tkm_value1	Output Tkm value for Normal cut and land cut for agie vision.

tkm_value2	Output Tkm value for Taper cut of land and taper for agie vision.
high_speed1	Output high speed machining for Normal cut and land cut for agie vision.
high_speed2	Output high speed machining for Taper cut of land and taper for agie vision.
smooth_finish1	Output smooth finish setting for Normal cut and land cut for agie vision.
smooth_finish2	Output smooth finish setting for Taper cut of land and taper for agie vision.
commutation_entry_distance	(ID_COMMPOINTENTRY)
commutation_exit_distance	(ID_COMMPOINTEXIT)
four_axis_z_lower	Four axis cutting z lower section value (ID_POSZ).
start_hole_diameter	Start hole diameter value (ID_DIAMETER)
set_collar_cutting_land	Output the collar setting for land.
set_collar_cutting_taper	Output the collar setting for taper.
collar_position	Z value for collar/land (ID_POSZ).
collar_taper_angle	Taper value for collar/land & taper (ID_TAPER).
collar_taper_height	Output the collar taper height.
collar_group_name	Output the collar group name.
end_point_x	End point X (ID_POSX).
end_point_y	End point Y (ID_POSY).
taper_collar_type	Collar/Land type (on top, on bottom).
die_clearance	Die clearance (ID_CLEARANCE).
prev_iso_file_name	Previous Iso file name.
collar_type	Output collar type for land and taper.
collar_land_height	Land height.
agie_work_name	Work piece name for taper in land and taper (LC1,LC2,LC3).
agie_group_name	Group name.
output_agie_taper_z	Output the taper Z value.
punch_die	Output the PUN / HOL value for punches and dies.
output_quality_one	Output that quality one is either quality is user defined or predefined.
output_quality_two	Output that quality two is either quality is user defined or predefined.
output_quality_one_coreless	Output that quality one for coreless is either quality is user defined or predefined.
output_quality_one_land_and_taper	Output that quality one for land and taper is either quality is user defined or predefined.
output_quality_two_land_and_taper	Output that quality two for land and taper is either quality is user defined or predefined.
output_die_clearance	Output die clearance in Agievision.
output_agie_taper	Output lines for taper in Agievision.
output_agie_leadout	Output lines for leadout in Agievision.

Agie	
cc_coreless_agie	Output the appropriate offset (G40,G41) of coreless cut depending on if it is the 1st, 2nd, of 3rd entity.
agie_start_of_file	Output the agie start of file block if it has not been output yet.
last_move_direction_coreless	Output the X,Y of the vector of the last movement of the coreless cut.
last_move_direction	Output the X,Y of the vector of the last movement of contour cut.
first_move_direction	Output the X,Y of the vector of the first movement of contour cut.
first_move_split_arc	Output the first move of the contour if it is an arc. Split the arc and output it as two arc moves.
x_f_distance_from_end	Output the X move of a line moving to a point a distance back from the actual end point.
y_f_distance_from_end	Output the Y move of a line moving to a point a distance back from the actual end point.
x_f_arc_distance_from_end	Output the X move of a arc moving to a point a distance back along the arc from the actual end point.
y_f_arc_distance_from_end	Output the Y move of a arc moving to a point a distance back along the arc from the actual end point.
arc_center_distance_from_end	Output the new arc center when arc cut distance from arc end is used.
prev_v_to_zero	Set the prev V movement value to 0.0.

Sodick	
sodick_taper_height	Output taper height as stock height, or land height depending on current settings, Use in header for TP value.
sodick_taper_opposite_height	Output taper opposite height as stock height, or land height depending on current settings, Use in header for TN value.
memorize_rethread_on_stop	Output the code for memorizing the rethread point when the wire breaks.

Charmille	
g27_on_no_taper	Output a G27 code when no taper is used on 2Axis contour.
taper_zero_blum	Output taper 0.0. Custom variable for Blum.

Ona	
technology_file_name	Output the technology file name that was entered on the ONA posting page.
xcenterup_minus_xcenterlow	Output X center value for upper section arc of 4 axis part incremental from X Center of lower section arc.
ycenterup_minus_ycenterlow	Output Y center value for upper section arc of 4 axis part incremental from Y Center of lower section arc.

Wire Guides

<code>metric_upper_guide_pos</code>	Output upper wire guide position in metric regardless of inch/metric mode
<code>upper_guide_pos</code>	Output upper wire guide position.
<code>lower_guide_pos</code>	Output lower wire guide position.
<code>guide_span</code>	Output the distance between upper guide, and lower guide.

Misc Characters

<code>cr_lf</code>	Output carriage return line feed characters.
<code>single_quote</code>	Output single quote character.
<code>quote</code>	Output double quote character.
<code>n_spaces</code>	Output spaces for the number of characters in the previous sequence numbers
<code>four_axis_delimiter</code>	Output delimiter character between upper and lower. Delimiter value define in "Misc parameters/4axis contour delimiter:".
<code>null</code>	Output a ascii charater 0 or NULL.

Misc Variables

<code>on_error_jump</code>	Output code for on error jump. Code defined in "M Codes/On error:".
<code>incr_upper_plane</code>	Output incremental value from program plane to upper plane.